

SUMMARY OF WORKS		
PE201 CAT D9N BULLDOZER		
DATE	HOURS/KM.	SUMMARY
17/04/2007		Instal new coolant temp gauge & replace wiring - <b>Westrac</b>
23/07/2007		Fabricate new ripper arm - <b>Rocor</b>
29/07/2007	1848	Machine apprasal - <b>Westrac</b>
18/06/2008	2612	Repair recoil spring - <b>Westrac</b>
18/08/2009		Service 1000 hrs
19/08/2009		Service 1000 hrs
28/08/2009		
18/09/2008	2612	Lineboring works on equaliser bar - <b>Ozzy Linebore</b>
20/09/2009	2612	Fit new bearing, seal & equaliser bar, pin & Track frame
22/09/2009		Adjust Brake
14/10/2009	3915	Check over & change transmisson filters
28/01/2009	4194	Turn cutting edge
19/01/2010		Repair & Replace windscreen wiper , Finish installing fire extinguisher ( Dave Holroyd )
5/01/2010	4195	Service ( Darryn )
30/01/2010		Fab & Fit handrails- <b>Force</b>
1/11/2009		Supply install & test A 6.5 Ltr ,Fire suppression A/FFF <b>WORMALD</b>
30/01/2010		Supply install & test A 6.5 Ltr ,Fire suppression A/FFF. <b>WORMALD</b>
30/01/2010		Check over . <b>WORMALD</b>
1/02/2010	4193	Fire suppression unit fitted <b>WORMALD</b>
		Hand railing fitted <b>FORCE</b>
		L & R Hand wiper motors replaced new front wiper arm fitted free up wiper linkages- Mick
		New revolving light fitted & wiring electric shut down solenoid fitted & governor shaft & fork removed & free up - Darryn ,Mick, Jon
		New washer bottle fitted , lings replaired make new washer tap selector handle 1 new fire extinguisher fitted repair lights paint handrails & lower frame - Jon
15/04/2010	4377	Wash & Degrease clean windows & blow out filters x2 - Mick Bennett
29/04/2010	4483	Exhaust stack loose & muffler damaged exhaust 500t leaking from muffler input. Fam drive belts worn out idler pulley bearings U/S Operator complaint R/H steering clutch slow to respond .Ripper shank guard worn out oin missing need new guard 2x pins & 2x locks . R/H blade tilt cyl leaking R/H blade cyl seal weeping - Andrew B
2/06/2010	4649	SERVICE oil leaking near front main seal ,replace pin in shank guard tranny pump noisy & cavitating - Andrew B
15/06/2010	4734	Change cutting edges & corner tips fit new bolts - Darryn
15-Jul	4927	service - tigh alternator belt ,clean the belly plates , change transmission filter & torque filter , change back left light ,change beacon ligt and fix it
23-Aug	4945	Remove inspect & reseal steering & brake cluthes both sides R/H brake disk & plates as new spec broken spring cushion replaced R/H steer cluthes replace all fricion plates due to erosion of surface L/H brake replace 2 damaged friction plates all others in new spec L/H steering cluth replace all disks & 5 plates due to erosion & distortion disassemble L/H final drive & inspect reset steerin g & brakes pressures after replacing transmission pump Repair engine oil leak & tighten half sump Tighten all coolant clamps replace seals on main relieve valve for hydraulics & set pressures replace several leaking o rings - Andrew
9/09/2010		Travel to Nullagine fit work lights in front of dozer. Deliver oil,grease , & points - Andrew
30-Sep		Service- Sample final drives & Tranny - Guillaume
5/10/2010		Replace fire extinguisher - Andrew
15-Nov	9006KMS	fix side ramps, change beacon, chane airfilter, change wiper blades sides and back
7/12/2010	5460	Remove broken left hand inner iddler mount cap bolt & replace with new bolt Rear trany guard belts were all broken off 5 of the bolts had been broken for some time was able to remove 4 x broken bolts . To install with new bolt - <b>EMS</b>
21/12/2010	5519	Service - <b>EMS</b>
10/01/2011	5519	Fit on the left hand side of the ripper an grease neeple extension - frenchie
29/12/2010		Prepare & order parts for job travel to Wodgina remove broken i/h inner idler mount cap bolt & replace with new bolt Remove 4 of the broken rear guard bolts - <b>EMS</b>
28/01/2011	5564	Diagnose falut & repair .Remove & replace gas in A/C system . Replace fitting on high side for compressor . Vac down & regas . Check for leaks . Find fault RH! condensor fan , fan U/S - <b>J &amp; S</b>
3/02/2011		Level 2 Service for VFS system - Missing key for bypass . Engine doesn't shut down must be looked at if not fixed . Checked system for leaks replaced gauge c As well as x1 S/S cap for nozzle. Checked for broken hoses on machine looking good . Level x2 Services on 9 kg DCP Extingusher - <b>Wormald</b>
11/03/11	5840	250HR service, cleaned, 1/2 bottle coolant top up, adjust alt belt. Ps 2 canon cracked around top half, pos i monor crack, did not have service sticker to replace old one <b>(FORCE)</b>
28/03/11	5840	Travel and carry out 250 hour service - <b>FORCE</b>
15/04/11		Drill out and replace broken idler bolt, travel to site,,, - <b>EMS</b>
28/05/2011	6168	<b>SEVICE - 500HR</b> - Clean & wash machine , fit new cutting edges , repair cracked cannon RHS , Fit new aircon switch . - BEN - DYLAN - FRENCHY
13/07/2011	0	<b>NEW HOUR METER FITTED ,</b>
13/07/2011	0	Drain r/h recoil frame & prepare for welding,weld crack in frame,repair thread,replace drain plug, fill with oil, resfit cap
21/07/2011	21 (new meter)	Fit new bearing, seals for the blade control. Chk over ready for job. Regas aircon, clean evaporator
22/07/2011		<b>FIRE SUPPRESSION SERVICE - WORMALD</b> - Level 1 Service 65Ltr Wormald LOP AFFF, Level 2 Service 4.5kg DCP Extinguishers
25-Jul	21	Weld Cannon cracks as reqd by <b>Force Equipment</b>
1/09/2011	194	<b>SERVICE</b> -Degreasing,washing,chk levels,lights,extinguishers, clean filters,greasing,wash coolant radiator, AC Condensor,undo RH side cutting edge for weldin check equalised bar shafts. Put corner edge back. Chk AC Rewel end on ripper shank, (Force)
31-Aug		
13-Oct	373	<b>SERVICE / OIL CHANGE</b> Change oil & fuel filters, top up pivot shaft oil carry out repairs to equalizer bar and track repairs <b>FORCE</b>
27-Dec		Chack Air con performance
31-Dec		4200 remove track frames & replace front major bogie pin, <b>(FORCE)</b>
31-Jan		Regrouser tracks <b>(FORCE)</b>
1-Mar		roller holder bolt hard to undo because of dry mud and find hard wood and steel to lift the track pads and new roller -Jud, Ruben & Fernando
27-Mar		get the engine belt from westrac and install- Ruben & Dylan
6-Apr	803	<b>SERVICE</b> - on site @ Dyno. Change oil and fuel filters, change engine oil, grease and clean air filter, check all lights and oil levels - Ruben Jeff Jerome
5-Nov		Replace seat